

# CERCLA DAILY WORK ORDER

Page 1 of 1

Site Name	Fruitland Magnesium Fire Incident	Contract #:	EP-S9-12-01
Location/Region:	Maywood, CA	Date:	Wednesday, July 27, 2016
ERRS:	Environmental Quality Mgmt	OSC:	Jason Musante
START:	NA	USCG	NA

## Description of Work to be Performed

1. Complete pumping contents of Baker Tank into vac truck - two loads today (approximately 8700 gallons)
2. Complete pressure wash and cleanout of Baker Tank. Tank expected to be offsite in AM of 7/28.
3. Complete transfer of 16 containers to site footprint from nearby businesses.
4. Secure site when complete

## Number of Authorized Personnel

Supervisors:	1	Operators:	FCA
Foremen:	1	Technicians:	4
			Truck Driver

## Authorized Equipment and Expendable Materials

Item	Quantity	Item	Quantity
Car, economy	1		
Computer	1		
5000 gallon Vac Truck (transporter)	2		
Double Barrel Truck	2		
Pressure washer, Double Barrel	1		

I certify that the above work is ordered and authorized by the OSC in the above cited contract.

*JASON MUSANTE*

Signature of On-Scene Coordinator

I certify that the above work is ordered and authorized by the OSC in the above cited contract.

*Peter Lawrence*

Signature of Contractors Representative

## Amendments

Signature of On-Scene Coordinator

Signature of Contractors Representative